



**标智®仪表**

**Humidity & Temperature Meter GM1360A**

**Specification**

Measurement range	Temperature:-30°C-80°C Humidity:0%-100%RH
precision	Temperature: $\pm 1^{\circ}\text{C}$ ( $\pm 1.8^{\circ}\text{F}$ ) Typical temerature: $\pm 0.3^{\circ}\text{C}$ (max $\pm 1^{\circ}\text{C}$ ) Humidity: $\pm 3\%$ RH (in 25,20-80%RH) $<\pm 5\%$ RH (in 25,0-20%RH~80-100%RH)
Resolution	Temperature: $0.1^{\circ}\text{C}$ / $0.1^{\circ}\text{F}$ Humidity: $0.1\%$ RH
Sampling time	1 times/sec
Operation conditions	-0°C-50°C (32°F-122°F) $\leq 80\%$ RH no condensation
Storage condition	Temperature: -30°C - 80°C (-22°F - 140°F) Humidity: 0%RH~90%
Power supply	9V 6F22 battery
Size	207*70*30mm
Weight	199.7g


**Feature**

- 1.Dual display on large LCD
- 2.Detecting the temperature and humidity
- 3.MAX/MIN measurement
- 4.Dew point pick up.
- 5.Data operation
- 6. $^{\circ}\text{C}/^{\circ}\text{F}$  unit switch
- 7.USB interface and data download
- 8.Low battery alert
- 9.Auto power off
- 10.Temperature and humidity memory (setup in PC program included)



**Temperature fig**

Temperature	Parameter
Measurement range	-30~80°C
precision	$\pm 1^{\circ}\text{C}$ ( $\pm 1.8^{\circ}\text{F}$ ) Typical temerature: $\pm 0.3^{\circ}\text{C}$ (max $\pm 1^{\circ}\text{C}$ )
Storage condition	Temperature: -30°C-80°C (-22°F-140°F) Humidity: 0%RH~90%
resolution	$0.1^{\circ}\text{C}/0.1^{\circ}\text{F}$



**LCD display**

- 1.Lock up icon
- 2.Maximum reading icon
- 3.Minimum reading icon
- 4.Average reading icon
- 5.Battery volume icon
- 6.Celsius temperature icon
- 7.Dew point icon
- 8.Fahrenheit temperature icon
- 9.RH unit icon
- 10.USB connection alert icon
- 11.Record icon

**The relative humidity table**

Humidity	Parameter
Measurement range	0~100%RH
precision	$\pm 3\%$ RH (in 25,20-80%RH) $<\pm 5\%$ RH (in 25, 0-20%RH~80-100%RH)
resolution	$0.1\%$ RH

